

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 4/28/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S03SS_004MH

Test ID: D1032-022017

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S03SS_004MH
3.799999952			Dye Test Visible	@ IR, 6gpm
6.5			Dye Test Visible	@ IR, 2gpm
6.900000095			Dye Test Visible	@ IR, 7 to 11oc, 2gpm
6.900000095			Dye Test Visible	@ IR, 4oc, 0.25gpm
11.19999981			Abandoned Survey	NO MORE DYE VISIBLE
21.20000076			Dye Test Visible	TF